


Silvercypress.

It is submitted to Belfast
Surveyors be requested to ascertain from
the builders of the machinery whether
any special materials were
incorporated in the engines which might
be adversely affected by a fire in
the engine room. [The intensity & extent
of the fire is not known in this office.
Nor is it known how the fire
was extinguished.]

20/3/37

W. Sullivan



© 2019

Lloyd's Register
Foundation

WS16-0328