


Lloyd's Register of Shipping,

5, Alexandra Buildings,

Hong Kong, 9th. March 1937.

The Secretary,
LONDON.



Dear Sir,

Motorship "SILVERCYPRESS"

The above vessel was badly damaged by fire which I understand originated in the engine room, and is now lying in Manila in her damaged condition.

The Hong Kong & Whampoa Dock Co. with a view to repairing the vessel, have asked what tests the Committee would require, particularly with regard to the engine forgings, outside of an examination for fractures and distortion of parts, and have suggested the following tests for which they have the necessary equipment :-

- (1) Brinell, Scleroscope, Magnetisation, Chemical Analysis and Microscopic tests of the various parts affected by fire.
- (2) One connecting rod and one piston rod be cut up and tensile and bend tests made from same and the results checked with the Brinell etc. tests.

Those who have seen the vessel say that it is possible the crank shafts have not been seriously affected as the fire tended to go upwards, this however will require to be decided on examination.

W515-0329

(2)

The cylinders, columns and other castings may be
badly damaged or distorted and may require renewal, but if
not, please state what tests of material would be acceptable.

I shall be pleased if you will reply by air mail.

Thanking you,

I am, Dear Sir,

Yours faithfully,

J. H. Morrison



© 2019

Lloyd's Register
Foundation

WS16-0329

R. S.

also for Mr. Spinks to note.

REQUESTING EARLY REPLY.

of your spiritual needs and emotions, especially of
 the heart, I cannot suppose you are hostile to them.
 I understand of him I intend to effect some of the
 things which you desire him to do, and I have no doubt
 that you will be very glad to see them.

1894

I was, now, at

1120187 67007

© 2019

Lloyd's Register
Foundation