

5 APR 1938

1

ed by Chief Ship Surveyor

Received from Chief Ship Surveyor

SEL'S NAME

"CHAGFORD"

Rpt. *Nwc*

No. *96045*

he remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

re of Survey

DAMAGE.

Damage through

Grounding

(See Dub. Rpt 5480)

now repaired as follows:-

	Shell Plates	Main Frames	R. Frames	Floors & Bracket Floors	Inner Bottom Plates	Deck Plates	Beams
Renewed	<i>2</i>						
Removed and faired or repaired.....							
Faired or repaired in place.....	<i>7</i>	<i>8</i>		<i>8</i>			

Other items:-

Vessel placed on slipway & minor

repairs carried out.

Bottom coated.


is submitted the vessel is worthy to remain as classed with

Record of Survey *3.38*

100A1

3.38 Nwc

31.3.38 *Wf*



© 2019

Lloyd's Register
Foundation

WS18-0246