

*Undertaking Base*

Surveyors 4. 12. 35

Received from Chief Surveyors

110 DEC 1935

NAME *% Whitegate*

Report *here*

No. 90213

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR**

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Survey *A Special Survey No 3*

When due *11. 3. 32*

*(after an early No 3)*

*1 General Examination*

A Special Survey No.3, after an early No.3, became due 11.32.

The ship being laid up, the Owners have furnished the usual undertaking.

The ship was last examined in drydock in October, 1930.

The case received consideration in January last, the Special Survey being then more than two years overdue, when no general examination was required.

In reply to enquiry the Newcastle Surveyors state that the vessel is still laid up in the Tyne.

It is submitted for consideration whether in view of the Special Survey being now three years overdue, the Owners should be asked to arrange for the ship to be generally examined.

*ms*

*5-12-35*

*[Signature]*

*Not yet*



© 2020

Lloyd's Register Foundation

W510-0013