

Undertaking Base

W520-0020

28. 12. 32

Received from Chief Surveyors

1 - JAN 1935

1/5 - Whitegate

Report

Misc

No. 90213

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been made to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case. The Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

A Special Survey No 3 When due 11.32
(after an early No 3)

? General Examination

Laid up since Jan 1930

A S.S. No.3, after an early No.3, became due 11,32.

The ship being laid up the Owners have furnished the
1 undertaking.


In reply to enquiry the Newcastle Surveyors write
the ship is still laid up in the Tyne.

The year of grace expired 11,33.

The ship was last examined in dry dock in October 1930.

It is submitted for consideration whether in view of
Special Survey being now more than 2 years overdue the Owners
should be asked to arrange for the ship to be generally examined.

My 299



© 2020

Lloyd's Register
Foundation