

W520-0175

BOARD REPORT on the

S.S. MAR CASPIO

It is submitted the report form & computation be sent to Mr. Crawford for Mr. Beraza to translate all the information thereon into the Spanish language & to insert it on a Spanish form C.11. He should also be requested to transmit the letter to the Spanish Authorities, informing them that it is considered the following should be done to comply with the requirements of the Convention:

An additional Spanish bery supplier for each of the trimming hatches ^{on the bridge} ~~in the forepeak deck~~.

He should also inform the Spanish authorities that as the freeboards - computed under the Convention regulations are less favourable than the existing freeboards, it is concluded the latter will be reassigned.

He should further request the Spanish authorities to advise this office & the Bilbao Surveypers regarding the freeboards approved & the conditions of assignment in order that the freeboards may be marked & the certificates issued.

The original freeboard report should be returned to this office as soon as possible. A photostatic copy of the report form should be retained in this office.

And this Owners & Blo

11-4-33

Spanish Convention



© 2020

GPB

Lloyd's Register
Foundation