

REGISTERED
RECEIVED
9 MAR 1934
LONDON

Time of Receipt.....

TELEGRAM.

POST OFFICE TELEGRAPHS.



If there is doubt about the telegram ring "Telegrams delivery for

accuracy of any part of this Enquiry" or call at the Office of free repetition.

This form, and if possible the envelope, should accompany any enquiry other than by telephone.

Prefix. Time handed in. Office of Origin and Service Instructions. Words.

15

No. 105

Office Stamp



To.....M

To.....

THE INFORMATION OVERLEAF WILL INTEREST YOU.

AGNES DUNCAN 20436 OWNERS DESIRE DISPENSE WITH
CEILING UNDER HATCHWAYS AND SUGGEST THICKNESS TANK
TOP PLATING WHEN BUILT ALLOWS FOR THIS CONFIRM BY
LETTER = REGISTER +



© 2021

Lloyd's Register

Foundation

W 520005

Referred to the Chief Ship Surveyor

- 9 MAR 1934

Also for Mr. Carney to note.

Submitted the Surveyor be informed that the ceiling could be dispensed with under the hatchways in view of the thickness of the inner bottom plating fitted when the vessel was built. Growth in the tank top plating be examined and found in good condition J.D.

W.V.
9.3.34

S.S. "AGNES DUNCAN".

Proposal to dispense with ceiling under hatchways.

Tel. 9.3.34.
Ansd. 9.3.34.



© 2021

Lloyd's Register Foundation