

2E

of Engineer Surveyor

Received from Chief Engineer Surveyor

Agnes Duncan

Rpt.

Cff

No.

50513

AME.

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.

COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No. *2*

This Survey, due *1-33* partly held at *By 5-33* now
 eted, and the following repairs carried out (due to *wear & tear*):—

*Some bearings reinstalled
 four furnaces failed &
 minor repairs.*

form:—

Where and when
 Superintended

It is submitted the vessel is eligible to remain as classed, with
 tion of *June 4-34* as recommended.

Subject to the
 DONKEY BOILER
 not being used again.

DA 574/34

CERTIFICATE WRITTEN
5.4.34

When and where
 Superintended



© 2021

Lloyd's Register
 Foundation

WS21-0011