

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

S.S. "Pylades"

Rpt.

hwc.

No.

77665

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.)—Extract from Sub-Committee's Report, 24/5/92.

Nature of Survey

S.S. No. *1* AND DAMAGE

Damage through *collisions*

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	<i>2</i>	<i>2 part</i>					
Removed and faired or repaired.....	<i>4</i>						
Faired or repaired in place.....	<i>1</i>						

Other items:-

One house pipe renewed and minor repairs.

The *2nd* S.S. No. *1* has also been held and following repairs done due to wear and tear:- *6 shell plates renewed, 1 removed & faired & 2 faired in place; 36 frames & 80 reverse frames repaired, side stringers partly renewed, stokehold bulkhead & side bunkers renewed in accordance with approved plans, hatchway coamings and bulkheads partly renewed & minor repairs.*

It is submitted the vessel is worthy to remain classed with record of Survey *3-74 hwc.* and notation of *S.S. hwc. 101-74.* as recommended.

*100 A1
3-74 hwc.
S.S. hwc. 101-74.*

*RM 020
21.3.74*
Lloyd's Register
Foundation

WS23-0015