

Howe Report No 53381.


On dealing with this Report, it is submitted that the  
two Surveyors should be requested to state whether casing  
has been fitted to Main Boiler Safety valves, as this item  
has been omitted from Report.

JSM

16/8/07

R.S.

16.8.07



© 2020

Lloyd's Register  
Foundation

WS25-0044