

Received by Chief Ship Surveyor 11. 10. 04

Received from Chief Ship Surveyor .....

VESSEL'S NAME Ste. S. S. "Grasmere" Report Moc. No. 47727

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


Nature of Survey

First entry.

It is submitted that before this case receives the consideration of the Committee it should be pointed out to the Surveyors that this vessel requires by Table 22 to be supplied with a towline of 75 fathoms of  $8\frac{1}{2}$ " hemp, or equivalent wire, and as this does not appear from their first entry report to have been supplied, they should be requested to state how the vessel can be recommended to the Committee as eligible for the figure 1 for equipment in her character.

Ltr. to Moc 11/10/04

C.H.J.  
11/10/04



© 2020

Lloyd's Register

W525-0086

Foundation



© 2020  
Lloyd's Reg  
Foundation

DEEP BRACKETS  
IN LIEU OF PILLARS