

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

14th June, 1923.

Dear Sirs,

S.

With reference to your Report No. 5347 on the steamer "STURE", I have to request you will let me know whether a new windlass has been placed on board, and the chain cables and anchors renewed.

At the same time I have to say it is concluded that it was not considered necessary to drill the shell plating, but you should state if this is so.


I am, Dear Sirs,

Yours faithfully,

Assistant to the Secretary

The Surveyors,

GOTHENBURG.



© 2020

Lloyd's Register  
Foundation

W527-0252