

COPY.

## Lloyd's Register of Shipping.

71, Fenchurch Street, E.C. 3.

14th January, 1936.

Dear Sirs,

S. With reference to my letter of the 20th ultimo conveying the Committee's agreement to your proposal to carry out the <sup>2nd</sup>/Special Survey No.3 of the steamer "STEFANOS COSTOMENIS" on her return to this side or the Mediterranean from the West Indies, I beg to acquaint you that a report has come to hand from Lloyd's Agents at Takoradi, West Africa, from which it appears that the vessel has been examined afloat and by a Diver on account of leakage in the fore peak.

Temporary repairs have been carried out by fitting a bolted doubling plate in way of the fractured shell plating in the fore peak on the port side which, on pumping out the fore peak, was found to be watertight, but I shall be glad if you will kindly state what arrangements you propose to make for permanent repairs to be effected.

I may add that, as previously recommended, some indented shell plating requires to be dealt with at the first convenient opportunity and the equipment of ropes placed in order.

I am, Dear Sirs,  
Yours faithfully,

Messrs. Rethymnis & Kulukundis, Ltd., Clerk to the  
Bury Court House,  
7/8, Bury Court,  
E. C. 3.  
Classification Committee.

WS29-0008