

cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for
ed?

Was a damage report made by anyone else? If so, by whom?

SS. "REGISTER, GLASGOW".

TELEPHONE: CENTRAL 6490 (4 LINES).

Lloyd's Register of Shipping.

LLOYD'S REGISTER
LONDON.

REC'D 19 OCT 1920
AIR

342, Argyle Street, Glasgow.

ENCLOSURE.

18th October, 1920.

Sir,

With reference to the enclosed Machinery Classification Certificate received for the Steamer "MANIPUR", Glasgow First Entry Report No.40400, I beg to acquaint you that this vessel is a sister vessel to the S.S. "MANGALORE", Glasgow Report No.40065, in which case you will recollect a special record was agreed upon in regard to the Builders of the Machinery and Boilers (please see your letter of the 2nd July). In these circumstances I conclude that the record on the classification certificate will be the same as that in the Register Book.


I think it well to add that the entry in the Register Book for the "MANGALORE", No.80425, does not appear to agree with your letter above referred to.

I am, Sir,

Your obedient Servant,

The Secretary,

LONDON.



Secretary to the
Glasgow Committee.

Lloyd's Register
Foundation

W53-0008

Referred to the Chief Ship Surveyor.
Referred to the Chief Engineer Surveyor.

13 OCT 1920

Mr. ~~Maxine~~
Lono

12/20/20

222
4/1



© 2020

Lloyd's Register
Foundation