

st Report No. \_\_\_\_\_ Port \_\_\_\_\_

Particulars of Examination and Repairs (if any) Docking Exp. BS

CHARACTER.  
\* for Special Survey  
Date of last Survey and of  
Periodical Surveys.  
2 E

2 E

Chief Engineer Surveyor \_\_\_\_\_

Received from Chief Engineer Surveyor \_\_\_\_\_

SHIP NAME "MANIPUR"

Rpt. \_\_\_\_\_ Lon. \_\_\_\_\_ No. 108357

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Survey COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No.

This Survey, due 10.39 <sup>now</sup> partly held 12.39 now

completed, and the following repairs carried out (due to) :-

It is submitted the vessel is eligible to remain as classed, with notation of BS 12.39 as recommended.

It is concluded that the oil fuel burning installation has been examined, but this should be confirmed.

*Yes*



© 2020

Lloyd's Register Foundation

28.2.40.

WS3-0014 / se

*examined found in order.*

*Bolt D is B in*

ALL SCRAWLS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.