

...Capacity ... 11 ...
N.D.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, masts, and of the inner bottom plating, especially in the boiler space.

CHARACTER.
for Special Survey.
Date of last Survey and of
Periodical Surveys.

PHONE: 36873 (2 LINES).



Lloyd's Register of Shipping.

Ocean Chambers, Lowgate,

Hull, 9th June, 1937.

LLOYD'S REGISTER
Received
10 JUN 1937
Ans'd.
LONDON

Dear Sir,

We beg to acknowledge the receipt of your letter of the 8th instant regarding the case of the steamer "MANIPUR", and have the pleasure to state that the deferred reports on this vessel were received from the Society's Surveyors at Middlesbrough this morning.

We are, Dear Sir,

Yours faithfully,

The Surveyors.

Per:-

The Secretary,

LONDON, E.C.3.



© 2020

Lloyd's Register
Foundation

W53-00 27

Referred to Mr. Spinks.

MS

10 JUN 1937

LONDON, E.C.2.

The Secretary,

Dear Sir,

I am sorry to hear

that you are unable

to attend the meeting

on the 11th of June at 10.30 a.m.

as you are away on business.

I am sure you will find the enclosed

of interest and will be glad to hear

of your views on the subject.

Yours faithfully,

Mr. Spinks



© 2020

Lloyd's Register
Foundation

LLOYD'S REGISTER
INCORPORATED IN ENGLAND
LONDON, ENGLAND