

Subject to collision damage on starboard bow being

RESPONSIBILITY WILL BE ACKNOWLEDGED FOR ANY CONSEQUENCES ARISING OUT OF STRIKES, COMBINATIONS, OR OTHER LABOUR DISTURBANCES

Telegrams: FRIGIARC, VICDOCK, LONDON
Telephone: ALBERT DOCK 2624

J. RUSSELL & Co., LTD.

ENGINE REPAIRERS, REFRIGERATING, ELECTRICAL, MOTOR & GENERAL
ENGINEERS, BOILER MAKERS, COPPERSMITHS & BRASS FOUNDERS,
PLUMBERS, TINSMITHS & SHEET METAL WORKERS.

BUTCHERS ROAD,

VICTORIA DOCKS,

LONDON, 1st. June. 1937.
E.16



Lloyd's Register of Shipping,
71, Fenchurch Street,
E. C. 3.

Dear Sirs,

S.S. MANIPUR - BOILER WATER.

To the instructions of Messrs. A. Goodwin -
Hamilton & Adamson Ltd. we have to-day collected
two bottles of boiler water from S.S. Manipur and
handed same to you.

Yours faithfully,

J. RUSSELL & Co., LTD.

J. Bicknell.



© 2020

Lloyd's Register
Foundation

W53-0045

W53-005

Referred to the Chief Engineer Surveyor.

slb

1 - JUN 1937

then for H
to write plat



© 2020

Lloyd's Register
Foundation