

Subject to collision damage on starbd bow being

6
2.

COPY.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C.3.

29th May, 1957.

176

ee.

Enclosure.

Dear Sir,

I have to acquaint you that the Society's Surveyors at Calcutta have reported that five rivets were found broken in one of the butt straps of a boiler of the steamer "MANIPUR" in December last and were replaced by screwed bolts. A further two rivets in the same joint have now been found broken and have been similarly dealt with. One broken rivet in another boiler was also replaced.

It is understood from the Society's Liverpool Office that the rivet heads and a sample of boiler water are in the hands of the Owners' Consulting Engineers, and I enclose herewith a copy of a communication which has today been addressed to the Secretary at Liverpool in regard to the matter.

In the circumstances I shall be glad if you will arrange for Mr. Lewis to give this case the necessary attention in due course.

I am, Dear Sir,

Yours faithfully,

The Secretary,
GLASGOW.



© 2020
pro Secretary.

Lloyd's Register
Founded 1863

W53-005