

3m, 2.25.

nt to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Stl S. MIDDLESEX

Report Li

No. 88353

For the CHIEF SHIP SURVEYOR Machine Engineer Sub-Inspector

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report 24/6/02.)

nature of Survey S.S.H. & alterations When due

*Noted.*



W. M. H.  
19. 4. 18.

Lloyd's Register  
Foundation

W 3 0143

Stringers \_\_\_\_\_  
Inner Bottom Plating also affixed

Have Ventilators and their Coamings been examined and found efficient? yes

Salting \_\_\_\_\_  
(State if examined.)

ditto \_\_\_\_\_

hawser & warps \_\_\_\_\_  
Standing & Running Rigging \_\_\_\_\_

General Observations Opinion as to Class Recommendation, &c.:-