

EBOARD REPORT on the S.S. "Hebe".

His submitted the surveyor be requested to state the scantling and spacing of the stiffeners on the bridge front bulkhead; he should also give full particulars of the openings, if any, in the bulkheads on frames 3 & 9 at after end of bridge, and the method adopted for closing same.

ERM W.D.

24.7.16



© 2021

Lloyd's Register

W530-0072
Foundation