

m.10.38

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "CHERITON"

Rpt. Abn

No. 19749

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee,

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The 2nd.S.S.No.2 became due 8,38, and a proposal to carry out the survey early this year has been agreed to.

Repairs are required to decks, bulkheads, bulwarks and casings.

The Aberdeen Surveyors now report the vessel placed on a pontoon after grounding, the bottom examined, considerable renewals are necessary including 20 shell plates, stern frame and rudder, floors etc. It has been decided that the vessel shall be broken up, and she has been towed to Leith for that purpose.

It is submitted a record of 'To be broken up' now be inserted in the Register Book.

*[Signature]*  
H.1.39

*[Signature]*



© 2019

Lloyd's Register  
Foundation

WS31-0064