

by Chief Ship Surveyor

Received from Chief Ship Surveyor

SHIP'S NAME

Steel S.S. "CHEWINTON"

Rpt. Mil.

No. 2911.

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Remarks of Surveyor

The Surveyor should be requested to state thickness of deck plating in way of Engine & Boiler Space, depth & thickness of floors, lengths of quarter deck & forecastle, whether the record of "cem" should be made in this case & if the ventilators have been examined as required by Circular 1339.

The Superintendent at Lloyd's Proving House, Cradley Heath, should be requested to forward particulars of Anchor Certificates Nos 25367, 25948 & 25953.

no action
14/8/32



ARB.

12-8-20

Lloyd's Register
Foundation
W531-0075