

Clan Mackellar.

To complete
outside patches to shell at scupper 526 P45
to be replaced by riveted spigot plates and
riveted patches to be fitted to scupper holes
in stringer plate.

See Inch 355-4
Liv 73918



© 2019

Lloyd's Register
Foundation

W531-0202