

*Compulsory*

Rpt. 12.

*copy*

# FREEBOARD VERIFICATION FORM FOR STEAMERS.

(When received in London Office)

Port Sunderland

Vessel's Name Batsford

Official No. \_\_\_\_\_ No. in Reg. Book \_\_\_\_\_

Port of Registry (For Foreign Vessels) \_\_\_\_\_

Iron or Steel Steel State whether Classed by Lloyd's Register Yp

Name of Owners Norris & Dixon Ltd Date of Verification 6/2/14

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line	3 ft.	$7\frac{1}{2}$ ins.
From centre of disc to top of statutory deck line } at awning or part-awning deck . . . }	✓ ft.	✓ ins.
Fresh water line above centre of disc . . .		$7\frac{1}{4}$ ins.
Indian Summer line above centre of disc . . .		6 ins.
Winter line below centre of disc . . . . .		6 ins.
<del>Winter North Atlantic line below centre of disc</del> . . . . .		ins.
Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of <del>wood</del> or iron deck with the vessel's side	at <del>main, spar or upper dk.</del>	2 ins.
	at awning or pt.-awning dk.	ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

(Signed) R. McLaren Surveyor.

(To be filled up in London Office.)

Statement No. \_\_\_\_\_ Date of Committee's Minute 30.1.14

Moulded Depth for record . . . . . 28 ft. 6 ins.

Freeboards compared and found correct by \_\_\_\_\_ date 9.2.14

Is fee paid? new vessel Form for Certificate A

Instructions \_\_\_\_\_ date \_\_\_\_\_

Certificate written \_\_\_\_\_ Noted for posting \_\_\_\_\_



*Classed for 10001 shelter deck  
conditional on the above freeboards.*