

D REPORT on the

"Infante Don Jaime"

It is submitted freeboard certificates be forwarded to the Trieste Surveyors for issue when the tween deck scuppers are found to be led to the bilges in accordance with the rules and referred to in Secretary's letter of the 3rd inst.

LWB
5-9-29.



© 2019

Lloyd's Register

Foundation

remaining scuppers situated between the superstructure and

E.-If the vessel is measured the details of the measurements reported.

1/2"

1"

1"

4"

9"