

F.E.

Ship Surveyor

Received from Chief Ship Surveyor

Steel S.S. "FANTEE"

Rpt. Nwc.

No. 72895

of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

orsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also  
ng out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points  
ated in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Case No. 80'08

Depth "d"

23'34'

Table No. 3 page 6

Description Bulb angle as approved.

Final No. 31999

Proportions Length =  
Depth =

11.2

erstrake as approved.

his vessel appears to have been built in accordance with the  
d the approved plans, and it is submitted she is eligible to  
ed ☒ 100 A.1. (steel) "Shelter Deck" with freeboard," as  
ded. The Summer freeboard of 9'-6½" from centre of disc  
f statutory deck line at Shelter deck, now marked on the  
sides, to be inserted in the classification certificate, and  
in the Register Book, and further, the remaining freeboards,  
on the accompanying verification form to be inserted in the  
cate of classification.

Dk (steel) and Shelter Dk (steel)

12 DB 35' 1290t. FPT 60t. APT 80t.

FK. Collision BH to Shelter Dk. 6 BH to upper Dk. Pl. Cms. Lloyds A/C.P. For Shelter Dk. 37'

The Certificate of Classification, to be endorsed  
"Cargo battens not fitted, and the same  
notation to be printed in the Register Book.

W533-0254

© 2019

Lloyd's Register  
Foundation

7-3-20