

Received from Chief Surveyors _____
 at to Chief Surveyors _____
 VESSEL'S NAME M/S 'INVERAYON' Report Lw No. 99991

For the CHIEF SHIP SURVEYOR and SHIP REGISTERED SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/93.)


Signature of Surveyor Condition When due _____

Subject to the stern frame repaired by E. H. 12.26 being specially examined at next drydocking.

Don 90823

[Signature]

[Signature]
 18.12.30



© 2020

Lloyd's Register
 Foundation