

# REPORT of SURVEY for REPAIRS, &c.

Writing Report 13 January 1916 When handed in at Local Office 19 Port of Amsterdam

Survey held at Amsterdam Date, First Survey 9 Oct Last Survey 19 Dec 1915

on the Wood, Iron or Steel *Timber hull* Master *B. Rietherk*

TONNAGE: - Built at *Dordrecht* By whom *S. V. Schuyt* When 1915

Owners *Red Indische Tank Maatschappij* Port belonging to *Gravenhage*

Surveyed Afloat or in Dry Dock? *By* Name of Dock *Drydock No. 2* Destined Voyage *U.K.*

B=Cell DBorDBa feet; uE&B feet; f feet; } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

al capacity tons. FPT tons; APT tons; MT feet tons. } CHARACTER. \* for Special Survey. Date of last Survey and of Vertical Surveys. Years assigned or expired. Machinery and Boiler Surveys (including date of N.B., if any).

ast Report, No. *10001* Port *Amsterdam*

When the vessel has been surveyed, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, keelsons, and of the inner bottom plating, especially in the boiler space.

When a damage report has not been made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS OR EXAMINATION AS PER RULE, FOR *Condition.*

*This vessel has been dry-docked for the purpose of cleaning & painting and also for inspection of bottom after grounding which occurred on one of the Guiderke trials. found One plate in flat of bottom B Strake on SB in No. 2 tank slightly indented & some rivets started, same repaired in place and started rivets renewed, Tank No. 2 tested under hydraulic pressure with satisfactory results. Bottom now in good condition scraped, cleaned and treated. Mudders & fastenings of seaconnections good. Freeboard marks verified & found correct.*

PRIMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faird or Repaired								
Faird or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Feet.) When put on, Month Year
Condition of Decks	Inner Bottom Plating	Engine Room Skylights	Boats
Condition of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Condition of Decks	State if Tanks now tested	Scuppers	Condition, how ascertained (State if wedges removed)
Condition of Decks	Bulkheads	Cargo Hatchways	Sails
Condition of Decks	Ceiling	Hatches	Equipment letter
Condition of Decks	Cement or Asphalt (State which)	Plating of Wood Vessels	Anchors, No. of
Condition of Decks	Steering gear and its connections	Caulking ditto	Cables (state if now ranged)
Condition of Decks	Windlass	Treenails ditto	" length size (on board)
Condition of Decks	Have Pumps now been examined and found efficient?	Braasthooks & Stemson ditto	" Rule length size
Condition of Decks	Have Sluice Valves now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Hawser & Warps
Condition of Decks	Have Watertight Doors now been examined and found efficient?	Timbers of Frame at openings ditto	Standing & Running Rigging
Condition of Decks		Ditto ditto at other places ditto	
Condition of Decks		Stringers, Clamps & Shelves ditto	
Condition of Decks		Salting (State if examined.) ditto	

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example: "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptxd15, &c."

*For the Committee's information.*

Survey Fee (per Section 38)	£	Fees applied for,	19
Special Damage or Repair Fee (if any) (per Sec. 38)	£	Received by me,	19
Surveying Expenses (if chargeable)	£		
Additional Surveyor's Fee (if any)	£		

Committee's Minute  
Character Assigned  
FRI. 21 JAN. 1916  
*Carrying petrol in tank*