

No. in Reg. Book.	Names of Vessels.	Notes of the parts of vessels requiring to be examined.	Last Port of Survey.
*35733	VALE OF MOWBRAY ...	Undertaking case. See special note at end of List	—
16153	VALENTIA	Ex. side bunkers to complete 3rd No. 3	Ips.
35737	VALENTIN RUIZ SENEN	Plating, &c., fore and aft (p.s.) to repair at first opportunity	Bbo.
*35740	VALETTA	Undertaking case. See special note at end of List.	—
*35744	VALLEJO	Undertaking case. See special note at end of List	—
35746	VALPARAISO	CS case..	—
16168	VAN DER GOES.....	No. 1 partly held. Two lengths steering chain to renew before completion SS	Ant.
35776	VANCOLITE	CS partly held. WTDB	—
*35778	VANCOUVER	Undertaking case. See special note at end of List. C3 (s.s.) to repair at a convenient opportunity...	Nwc.
*35781	VANDUARA	Undertaking case. See special note at end of List.	—
35783	VANELLUS	Permanent repairs to plating, &c. (p.s.f.), at Owners' convenience.....	Mch.
*35789	VARAND	Undertaking case. See special note at end of List.	—
35793	VARDAAS	No. 1 and CS partly held	Fal.&Cco.
35794	VARDAR	DB not to be used	—
35796	VARDULIA	Stern frame and shell plate No. 8 in 3rd strake below sheerstrake (s.s.) (EW 2.34) and No. 12 plate in 4th strake below sheerstrake (EW 12.34) to specially ex. next docking	Sws.&Gls.
35798	VARG	CS partly held. Progressive Survey of oil tanks. Oxter plates (EW 4.34) to specially ex. next docking.....	Liv.&Got. Hav.
35807	VARVARA	2nd No. 3 partly held	Mmo.
35809	VASAHOLM	Lowest stern plate (p.s.) (EW 9.33 and 4.35) to specially ex. next docking	Got.
35810	VASALAND	Indented plates E10 and F10 (p.s.) and A5 and B5 (p. & s.). CS partly held	Val.
35811	VASCO.....	Rudder mainpiece (EW 10.33 and 10.34) to specially ex. next docking.....	Ham.&Ant.
35815	VASSILIOS DESTOUNIS..	Indented bottom plating (s.s.) at fwd. end of No. 2 DBT and after indented forecastle side plate (s.s.) Lower part of rudder mainpiece (EW 8.35) to specially ex. next docking	Rot.&Ant.
35826	VEERHAVEN	Indented plating (p.s. aft). Plates No. 2 in 3rd strake below sheerstrake (p. & s.) to specially ex. next docking	Adn.
35836	VELHO	BS 1.35 when Bs repaired	L.An.
35837	VELMA	Stbd. propeller to specially ex. next docking	Liv.
16223	VELIA	Indented plating. Also see Limitation List	Rga.
35839	VELTA	BS partly held. DB not to be used	Lth.
35843	VENDIA	Permanent repairs to plating (s.s. in way of No 3 hold) at Owners' convenience	Gms.
16230	VENDORA.....	Indented plating.....	Hbg.
35845	VENERN	BS 9.35 when stbd. B surveyed and all valves ad- justed	Skm.
35846	VENERSBORG... ..	Indented plating (p. & s.). Electric light installa- tion to be exd. and tested to complete 2nd No. 2.	Rot.&Cco
*35847	VENETIA	Undertaking case. See special note at end of List. Permanent repairs to shell plating at Owners' convenience	Ams.
35849	VENEZUELA	BS partly held. Plating to be drilled when vessel is 36 years old or at next SS thereafter	Kob.&Nag.
35851	VENICE MARU.....	Repairs to stern frame to specially ex. next docking. Buckled beam knees in holds and 'tween decks to repair at next AS	—
*16232	VENOSTA	Undertaking case. See special note at end of List	Gms.
16239	VENUS	Oxter plates (EW 6.31 and 7.34) to specially ex. next docking	Gms.&Rjk.
16249	VER	Rudder mainpiece (EW 8.35) to specially ex. next docking. Stem and indented shell plates fwd. (p. & s.) to be dealt with	—
16253	VERA GRACE	See Limitation List	Fiu.
35871	VERDI.....	Indented plates E3 and 7, F3 and 8 and D8 (s.s.) ...	Bal.
35874	VERMAR	2nd No. 1 partly held.....	Trondhjem
35876	VERNA	Indented plates, &c. (p. & s.)	Got.
35877	VERNA	Indented shell plate F9 (p.s.). Also see Limita- tion List	Mmo.
35890	VESTANVIK.....	Indented plating (p. & s.)	Osl.
35893	VESTFOLD	No. 1 and PrBS partly held	Nap.
16298	VESUVIO	No. 1 partly held	Cpn.
35902	VESUVIUS.....	See Limitation List	—
35909	VIBORG	2nd No. 1 partly held	—

The particulars given above are only intended to be a guide to the Surveyors. Further information must in all cases be obtained before the inspection is proceeded with.

W537-0153