

4 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

'S NAME "LUCELUM"

Rpt. Nwc.

No. 94346.

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.


"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.32.

Survey ~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

Donkey Boiler Survey held.

General examination of steering gear, ~~main~~ windlass and pumps made. with a view to the vessel being towed to the United Kingdom or the Continent for breaking up.

It is submitted action be deferred.



© 2020

5.11.36.

Lloyd's Register
Foundation

W537-0182