

(AT.) No. 173.

Lloyd's Register of British & Foreign Shipping,

56, John Street,

Sunderland, 19th. August, 1903.

LLOYDS REGISTER
LONDON.

REGR 20 AUG 1903

ANSR

The Secretary,

London.

Sir,

In reply to your letter of yesterday's date in connection with my Freeboard Report No. 21233 on the S.S. "ST. AGNES", I beg to state that the stiffening of the bridge front is in accordance with the Secretary's letter of 6th. February, 1903 viz:- Bulb angle $8\frac{1}{2}$ x 3 x 10/20 spaced 30" apart and kneed top and bottom.

I regret the omission.

I am, Sir,

Your obedient Servant,

J S Shute



© 2021

Lloyd's Register
Foundation

WS38-0302

WS38-0303

Referred to the Chief Ship Surveyor.

Y/D

120 AUG. 1908

GRM

22225

1000, 1000, 1000, 1000

1000, 1000, 1000, 1000

1000, 1000, 1000, 1000



© 2021

Lloyd's Register
Foundation

Total excess

=

10.0

"

HAVI