

W539-0220

C. 7c, 11.28.

FREEBOARD REPORT on the S/S SPILSBY

It is submitted the Freeboards given on the accompanying

form, being those required by the Tables, merit approval, subject to

(1) The battening arrangements to No 1 Main Hatchways, & to the Hatches on the ~~Bridge~~ Poop deck leading to the Tween deck spaces, being placed in good order.

(2) The ventilation in the forecabin deck to the fore peak being renewed, & efficient means of closing being provided for all ventilators.

✓ (3) The engine room skylight being repaired to the Surveyors satisfaction.

✓ (4) The closing appliances of the doors in the forecabin bulkhead being repaired.

(5) Tarpaulins, covers, & battening arrangements being provided for the hatches in the Bridge Tween deck space as required by the Convention.

(6) The rest bars of the Bridge deck hatch to the Bridge Tween deck space being renewed.


(7) One additional tarpaulin being provided for each of the poop deck hatchways. For the bunker hatchway on the bridge deck.

The freeboards as computed under the Convention existing freeboards, do latter have been

being greater than the <sup>2020</sup> G.B. re-assigned. J.M.M.

CONVENTION

MRC 13/6



Lloyd's Register Foundation U.S.N. 13 6