

# REPORT of SURVEY for REPAIRS, &c.

Date of Writing Report 10th Aug 1904 When handed in at Local Office 10th Aug 1904 Port of WEST HARTLEPOOL  
No. in Survey held at W. Hartlepool Date, First Survey and Last Survey 8th Aug 1904  
Reg. Book. 1471 on the Wood, Iron or Steel SS "STORK" (No. of Visits one) Master ✓

TONNAGE:—  
GROSS 2050 Built at Stockton By whom Rogner & Son When 1904 MONTH ✓  
UNDER DECK ✓ Owners General Str New Castle Port belonging to London  
NET ✓ Owners' Address —  
(If not already recorded in Appendix to Register Book.)

Surveyed Afloat in Dry Dock? Name of Dock Wrights Destined Voyage Stockton

WB=CellDBorDBa feet; uE&B feet; f feet; f feet; f feet;  
total capacity tons. FPT tons; APT tons; MT tons.

N.B.—All alterations in the existing records should be underlined.  
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thickness of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.  
\* for Special Survey.  
Date of last Survey and of Periodical Surveys.  
Machinery and Boiler Surveys (including date of N.B., if any).  
100A 1st Aug 04  
with freeboard  
(Class contemplated)  
Society's Freeboard (if assigned) as painted on Ship and now verified

Last Report, No. Port

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? also whether any damage report was made, and, if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Locking  
Vessel placed in dry dock, bottom cleaned, examined and recoated.

## SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Removed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

## PRESENT CONDITION OF THE

Decks <u>good</u>	Stringers <u>good</u>	Dbleg. Plates under Sounding Pipes <u>not seen</u>	Copper, or Y.M. of Wood Vessels (State if on Port.) <u>✓</u>
Caulking of Decks <u>✓</u>	Inner Bottom Plating <u>not seen</u>	Engine Room Skylights <u>good</u>	When put on, Month <u>✓</u> Year <u>✓</u>
Waterways <u>✓</u>	State if Tanks have been examined inside <u>no</u>	Coal Bunkers, Open'gs, Lids, &c. <u>✓</u>	Boats <u>good</u>
Coamings <u>✓</u>	State if Tanks now tested <u>no</u>	Scuppers <u>✓</u>	Masts, Yards, &c. <u>good</u>
Beams & Fastenings <u>✓</u>	Bulkheads <u>good</u>	Charge Hatchways <u>✓</u>	Condition, how ascertained <u>on deck</u>
Outside Plating <u>✓</u>	Ceiling <u>✓</u>	Hatches <u>✓</u>	(State if wedges removed <u>no</u> )
Caulking of ditto <u>✓</u>	Cement or Asphalt (State which.) <u>not seen</u>	Planking of Wood Vessels <u>✓</u>	Sails <u>good</u>
Rivets <u>✓</u>	Rudder <u>good</u>	Caulking ditto <u>✓</u>	Equipment letter <u>✓</u>
Breasthooks & Crutches <u>not seen</u>	Windlass <u>✓</u>	Treenails ditto <u>✓</u>	Anchors, No. of <u>35 18 14</u>
Transoms <u>✓</u>	Have Pumps now been examined and found efficient? <u>not seen</u>	Breasthooks & Stemson ditto <u>✓</u>	Cables (State if now ranged) <u>no</u>
Frames <u>good</u>	Have Sluice Valves now been examined and found efficient? <u>not seen</u>	Transoms, Pointers, & Crutches ditto <u>✓</u>	" length (on board) size <u>✓</u>
Reverse Frames <u>✓</u>	Have Watertight Doors now been examined and found efficient? <u>not seen</u>	Timbers of Frame at openings ditto <u>✓</u>	" Rule length (per Table 22) size <u>✓</u>
Floors <u>not seen</u>		Ditto ditto at other places ditto <u>✓</u>	Hawsers & Warps <u>good</u>
Keelsons <u>✓</u>		Stringers, Clamps & Shells ditto <u>✓</u>	Standing & Running Rigging <u>✓</u>
		Saltg. (State if examined.) ditto <u>✓</u>	

## General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1, 98," or "to remain as classed and to have record of survey, 1, 98, and the notations of ss No. 1-98 and ptND98, &c."

The foregoing remarks are respectfully forwarded for the information of the Committee

Office Fee (if chargeable) per Scale II., Sec. 27 ..... £  
Survey Fee (per Section 28) ..... £  
Special Damage or Repair Fee (if any) (per Sec. 28.) ..... £  
Travelling Expenses (if chargeable) ..... £  
Second Surveyor's Fee (if any) ..... £

Fees applied for,

19

Received by me,

19

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character Assigned

FRI. 19 AUG 1904



© 2020

Lloyd's Register

Foundation

W 539-0272