

25 JUN 1935

No. 92664

(Received at London Office)

REPORT of SURVEY for REPAIRS, &c.

NEWCASTLE-ON-TYNE

Date of writing Report 21 June 35 When handed in at Local Office 21 June 1935 Port of NEWCASTLE-ON-TYNE

No. in Survey held at Wallsend on Tyne Date, First Survey 22 May Last Survey 13 June 1935

Reg. Book. 50461 on the Wood, Iron or Steel T.S.S. "Maimon" (No. of Visits 2)

TONNAGE:— Built at Newcastle By whom Palmer's Co. Ltd. When 1920 9

GROSS 8011 Owners James Savill & Albion Co. Ltd. Owners' Address (if not already recorded in Appendix to Register Book)

UNDER DEK. 7452 Managers Port belonging to Southampton

NET 5000 Managers Afloat at N.E. Quay. Destined Voyage

Surveyed Afloat or in Dry Dock? Afloat Name of Dock N.E. Quay. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

WB=Cell DBor DBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

Report, No. 55238 Port Gls.

Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent repairs. Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs.

In cases where the Surveyor has not made a special damage report he is required to state whether he has made a special damage report and to whom and why they were declined.

Was a damage report made by anyone else? If so, by whom?

OR EXAMINATION AS PER RULE, FOR

Vessel examined afloat.
Stockhold bulkheads at 92 & 111 frames recessed
for fitting of superheater elements as indicated
on approved plans now returned.
A number of minor general repairs also effected.

OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
... ..								
... ..								
... ..								
... ..								

Decks	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels
Stemings	State if Tanks now tested	Dblng. Plates under Sounding Pipes	(State if on felt).
ing	Bulkheads	Engine Room Skylights	When put on, Month Year
in way of sidelights	Ceiling	Oil Bunkers	Boats
	Cement or Asphalt	Scuppers	Masts, Yards, &c.
	(State which.)	Cargo Hatchways	Condition, how ascertained
	Rudder	Hatches	(State if wedges removed)
	Steering gear and its connections	Planking of Wood Vessels	Sails
	Windlass	Caulking	Equipment letter
	Have pumps now been examined and found efficient?	Treenails	anchors, No. of
	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson	Chain Locker
	Have Watertight Doors now been examined and found efficient?	Transoms Pointers, & Crutches	Cables (State if now ranged)
	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings	length mean diam.
		Ditto Ditto at other places	(on board) size
		Stringers, Clamps & Shells	Hawser & Warps
		Salting	Standing and Running Rigging
		(State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptn24, &c."

This vessel is eligible, in my opinion, to remain as classed without fresh record of Survey.

Survey Fee (per Section 20) £ 3 3 0
Special Damage or Repair Fee (if any) £
Travelling Expenses (if chargeable) £
Second Surveyor's Fee (if any) £

Committee's Minute/ TUE. 9 JUL 1935

Character Assigned note H.P. J. P. G. L.

Fees applied for,


10

Received by me,

12-7-35

13/4

Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

W54-0098

2

ANCHORS.

11 Stockless, state Mechanical Tests

CHAIN CABLES.

Iron Stream Chain }
or Steel Wire.... }