

5 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

- 6 - 1111 1935

NAME

Main moa

Rpt.

hwe

No.

92664

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/32.

DAMAGE & WEAR AND TEAR.

*Repairs fitted to main boilers in accordance with approved
The necessary alterations to main engines & pumps effected
in usage of Superheaters. Main repairs effected*

is submitted the vessel is eligible to remain as classed with *en.*

1 of Survey

as recommended.

4. dia of H.P. & 1st I.P. Cyls. 16

24 24 33 1/8 respectively

Lloyd's Register
Foundation

W54-0114

caters :- Superheaters of the North Eastern Marine Smoke Lubrication