

Chief Surveyors 20. 1. 37

Received from Chief Surveyors

VESSEL'S NAME *M. Linné 'JOHANNA THORDEN'* Report *Bal* No. *6207***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

Nature of Survey

Damage (temporary repairs) When due

Subject to port haize pipe being renewed on the vessel's arrival at her home port at the termination of this voyage

This vessel was wrecked at the Orkneys 12. 1. 37.

NAB
[Signature]
20. 1. 37.



© 2020

Lloyd's Register
W544-0124
Foundation