

Messrs. A.-B. Oresundsvarvet.

Yard No. 41.  
-----

IT IS SUBMITTED the <sup>MALMO</sup> Copenhagen Surveyors be informed that the test sheets for the generators and motors attached to report No. 1510 do not all give the requisite information, and that the records in some cases are missing. These are:-

1. Test records are missing for

12 Kw. auxiliary generator.  
2 -  $2\frac{1}{2}$  H.P. Oil Separators.  
2 - 10 H.P. Ventilation Fans.  
10 H.P. Oil Fuel Transfer Pump.

These records should be obtained and submitted for approval.

2. The test record for Messrs. Svenska Elektromekaniska Industriaktiebolaget's Machine No. 106733 does not contain details of all the tests required by the Rules. This is a 9 H.P. Bilge Pump Motor.

The Firm should be asked to submit details of tests on this machine to show that it would meet with the requirements of the Rules.


3. The test records for Messrs. A.S.E.A. machines 587108-109 are also lacking in the required information. It is concluded that one of the above is for a 1 H.P. refrigerator circulating pump. This Firm knows the Society's requirements as similar cases have been dealt with previously, and they should be asked to furnish information which would show that the motor would comply with the requirements of the Rules.

The Surveyors reply is awaited.

Return 2 test records.

*The Surveyors should also be requested to forward the report 4C in respect to the generator engines*

*R.I.H.*  
3rd December, 1936.



Lloyd's Register  
Foundation

Scavenging Air Pumps, No.

Diameter

No.

Position