

No. of Feed pumps 2 ✓ Diameter of ditto 4 1/2" Stroke 25" Can one be overhauled while the other is at work

COPY OF TELEGRAM DESPATCHED.

A Telegram, of which the following is a duplicate, was sent you this day, and the same is hereby confirmed.

h.	m.	m.	No. of Words	Date 13 th July 1906
M JOSEPH L. THOMPSON & SONS, Ltd., M H SANDS SHIPBUILDING YARD & MANOR QUAY REPAIRING WORKS, <small>TELEGRAPHIC ADDRESS: THOMPSONIAN, SUNDERLAND.</small> SUNDERLAND.			To Committee. London.	

KNIGHT AND FORSTER, PRINTERS, LEEDS.

Siam Classification

Certificates - Will you kindly send these over to Glavin Brothers tomorrow and oblige.



© 2020

Lloyd's Register
Foundation 545-0158

Date of test 10-10-05 Can each boiler be worked separately *Yes* Area of fire grate in each boiler 62 ft² No. a