

ternpost.  $53.5 \div 2 = 26.75$  Mean

Thickness of usual wood deck, less stringer.....

-  $3\frac{1}{2}$ "

EBOARD REPORT on the


$\frac{3}{8}$  Sterndale

Richardson Duck & Co 607

It is submitted the Freeboards given on the accompanying form being those required by the Tables merit approval.

*[Handwritten signatures]*

5.7.10



© 2020

Lloyd's Register  
WE45-0331

Other Corrections (if any).....

15.68

15.72

for R. O. Dk. if engine and boiler openings not

$2\frac{1}{2} \div 11\frac{3}{4}$  ✓