

Subject to the Keel plates (found slightly frayed forward)  
being specially examined at the next dry docking.

11

by Chief Ship Surveyor

Received from Chief Ship Surveyor 15 MAY 1937

EL'S NAME

" KARoola "

Rpt.

Syd.

No. 15486

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report. 24/5/92.)

of Survey

Docking.

The

Sydney

Surveyors report this vessel placed in

y dock, bottom cleaned and coated and minor repairs effected.

The Keel plates, as above, examined & found satisfactory.  
It is submitted the vessel appears worthy to remain as

assessed with record of survey

3.37

as recommended.

Subject as above

100 A.1  
Cloning Dr. with  
spec board  
3.37 Syd.

Subject re

Att  
Jld

14.5.37



© 2021

Lloyd's Register  
Foundation

W551-0003