

4E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

EL'S NAME "ELENGO A KYDONIEFS".

Rpt. Ant.

No. 22232.

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.92.

REPAIRS TO ENGINES ~~AND BOILERS~~ DUE TO DAMAGE THROUGH GROUNDING.

Engines partly examined; some shaft coupling bolts renewed and some tunnel bearings remetalled.

A large number of condenser tubes renewed and minor repairs and adjustments effected.

It is submitted the vessel is eligible to remain as classed with record of survey S 9,38.

Ws57-0121



Ymm
4.10.38.

Lloyd's Register
Foundation

THE SURVEYORS ARE RESPONSIBLE