

All wooden decks, upper and lower bridge found
slightly sprung.

SPECIAL NOTE.

Casualty

Notice

29 6. 38.



© 2019

Lloyd's Register
Foundation

W552-0125