

All wooden decks, upper and lower bridge found
slightly sprung.

SPECIAL NOTE.

Sl. No 3 to be held not later than 6.40



© 2019

Lloyd's Register
Foundation

W552-0126