

Leonard Ralph Horne of Lloyd's Register of Shipping, 85, Fawcett St., Sunderland, will say :-

I am a Master of Engineering of Liverpool University.

I am a ship and engineer surveyor to Lloyd's Register of Shipping and am stationed at Sunderland.

I examined the S.S. "TAYLOR" on Crown's Slipway, Sunderland on 22nd and 23rd December, 1936. I examined the outside fastenings of the propeller, stern tube and stern bush and of the sea valves and cocks, and I have no note or recollection of any defects in, nor of any repairs being effected to the parts mentioned.

I again surveyed this ship on the same slipway from 15th to 16th April, 1937. I examined the propeller, screw shaft, sterntube bush and outside fastenings. The propeller was found to have 2 blades broken off and a new propeller was fitted. The screw shaft was tested in the lathe and found true and the sterntube bush was rewooded. No other repairs were found to be necessary.

10. 3. 38.



© 2019

Lloyd's Register
Foundation

W552-0204