



Lloyd's Register of Shipping.

55, Fawcett Street,

Sunderland, 9th March, 1938.



Reference


Dear Sir,

With reference to your letter "M" of the 7th instant regarding the S.S. "TAYLOR", I have to say that at the survey in December, 1936 I examined this vessel on Crown's Slipway and I noted in my Journal on 23rd December, 1936 "Prop. and outside fastenings in order. Wear down 1/4" ".

The outside fastenings mentioned were those of the propeller, stern tube and stern bush and of the sea valves and cocks. The survey of these items was confined to the usual external examination and I have no note (or recollection) of any defects in, nor of any repairs being effected to, the parts mentioned.

I again examined the vessel on Crown's Slipway on the 13th, 14th and 16th of April, 1937. On the 14th, I noted in my Journal "Outside fastenings in order". This survey was also confined to an external examination of the fastenings and again I have no note (or recollection) of any defects in, nor repairs being effected to, the sea valves or cocks.

On this occasion the propeller was found to have two blades broken off. I made the following entries



9th March, 1938.

in my Journal:-

Tues. 13th. "2 Blades off propeller: Same to be renewed and Shaft gauged for truth."


Wed. 14th. "T.S. tried in posn. and appeared out of (3 visits) truth. Checked in lathe and found true, wear in way of packing being uneven. Bush to be rewooded".

and on the 16th. "new propeller fitted".

After each survey I stated to the Committee in my Report that "the machinery of this vessel, as now seen, is in an efficient condition and eligible, in my opinion, to remain as classed", adding, in December 1936, "without fresh record" and in April, 1937 "with fresh Record of C.L. 4,37" (indicating that the screw shaft was fitted with a continuous brass liner and had been examined and found in order).

I am, Dear Sir,

Yours faithfully,



The Secretary,
LONDON.



© 2019

Lloyd's Register
Foundation

W552-02062

Referred to the Chief Ship Surgeon

M255-0509 1/2

10 MAR 1938

Handwritten initials

TOPICAL

Unreferred

Dear Sir,

I am, Dear Sir,

...and has been examined and found in order. (L...)
...indicating that the vessel was fitted with a continuous
...record and in 1931. With these records of C.I. & S.A.
...remain as evidence, ... in December 1930. Although these
...is in an efficient condition and suitable in its opinion, to
...in the records that the ... of this vessel, as now seen,
... After this matter I refer to the Committee

...on the 10th. ...

...to be ...

...in view of ...

...that ...

...to the ...

...and ...

...to be ...

...

...



© 2019

Lloyd's Register Foundation