

Surveyor

Received from Chief Ship Surveyor

3 - MAR 1934

Steel Sc. Sr. "FRATERNITY"

Rpt. Mtl

No. 3838

Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

ment to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


The 3rd S.S. No.1 became due 3,33 and in view of the general carried out at Manchester in May 1933 a proposal to carry out the vey within the year of grace has been agreed to.

The Montreal Surveyor now reports ⁽²⁷⁻¹⁻³⁴⁾ the vessel examined afloat ount of encountering ice, a bower anchor and 130 fathoms of chain

The Surveyor recommends a bower anchor and 130 fathoms of be supplied before the opening of navigation.

It is submitted action be deferred.

One bower anchor and 130 fathoms c.c. to supply"



Repk. J.H.
© 2021 2.3.34

Lloyd's Register
Foundation