

COPY.

24 FEB 1934

Lloyd's Register of Shipping.

Port MONTREAL.

February 7th, 1934.

This is to Certify that

GEORGE ALLAN

the undersigned Surveyor to this Society did at the request of its representative survey the steel screw steamer "FRATERNITY" gross register of Manchester, England for the purpose of ascertaining the nature and extent of damage stated to have been sustained encountering heavy ice below the Lower Traverse in the St. Lawrence River and causing the vessel to break her Port anchor cable and Port anchor of one hundred and thirty fathoms of cable and Port anchor.

For further particulars see official log books and protest. On examination of the vessel while afloat in Outer Basin, on the 26th January, 1934 the undersigned Surveyor FOUND:-

DAMAGE

RECOMMENDED

Port anchor missing.

To be supplied and fitted.

One hundred and thirty fathoms of cable missing.

" " " " "

The above recommendations have been made with a view to the vessel in the same good and efficient condition as before accident in question.

(SIGNED) GEORGE ALLAN

SURVEYOR TO LLOYD'S REGISTER.

This certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-
The Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is not to be held responsible for any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Committee or any Member thereof, or of other Officers or Agents of the Society."