

(1000-9-03.)

1.

Sent to Chief Surveyors *8. 12. 03*

Received from Chief Surveyors

VESSEL'S NAME *Sa. S. S. "Fraternity"* Report *Enk* No. *13783*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

First entry

When due

+ 100 A1 ("Steel")

1 DR (Stl) + web frames.

N. B = Cell DB a 29' u E17' f 81' 152L FPT 14L APT 33L

FK 4BH Cene. Doyls A+CP Q52' B59' F20'

REMAIN

C.A.f.
8/12/03

© 2021

Lloyd's Register
Foundation

WSSB-0208

Spacing	22	22	22	22		
PILLARS, In 'tween Decks, Size and Spacing	2 1/4	-	44	2 1/4	-	44

Tie plates	22	22	22	22
Deck, Material and thickness	22	22	22	22