

F.E.

Ship Surveyor 8.2.18

Received from Chief Ship Surveyor

ME Steel S.S. Orchis

Rpt. Cpl

No. 3190

s of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

orse No. 38.25

Depth "d" 11.5

Table No. 3 page 10

Description Single angle + Bulb angle, as approved

dinal No. 5737

Proportions $\frac{\text{Length}}{\text{Depth}} = 11.5$

Deck Sheerstrake as approved

this vessel appears to have been built in accordance with the
 and the approved plans, and it is submitted she is eligible to
 ed 100 A-1 (Steel) as recommended.

I.DK (Steel) well dk.

FRT 106

FK 3BH. can. Legated 283' B' 9' F 24' Mch. aft.

Date of Build 8.17.



12/4/23.

8.2.18



© 2021

Lloyd's Register

W557-0057