

Surveyed Afloat or in Dry Dock?

Ship Name of Dock

W558-0159 1/2

Chief Surveyors

10 to 02

Received from Chief Surveyors

VESSEL'S NAME

% Indrasakha

Report

Long No. 1479

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey

When due

It is submitted the Owner be informed in reply to his letter that it is not considered necessary the vessel should be submitted to examination by the Society's Surveyor at Hong Kong, but provided it be arranged for the examination in question to be made on her return to the U.K., the same will be considered satisfactory.

St. J. C. N. J.  
C. M. 11. 4. 02  
L. to Own - 12/4/02  
J. L. 11. 4. 02



© 2021

Lloyd's Register  
Foundation

Survey Fee (per Section 25) £

Special Damage or Repair Fee (if any) (per Sec. 25.) £ 15 15 0

Travelling Expenses (if chargeable) £ @ 1/9 1/2

7. 3 1902

Received by me,

10. 3 1902

Howe